

NETWORK DOCUMENTATION

Equipment Inventories, Rack Elevations, Network Diagrams & Process Overviews

Sandbox Technologies
3868 W Carson St, Suite 316
Torrance, CA 90503
www.sandboxtech.com
Tel. 424.207.5130

SANDBOX TECHNOLOGIES

Small Business Solutions
Enterprise GrowthPath®
EGP Secure®
EGP Cloud™
ConstructIT®


Professional Network Documentation

Proper documentation is key to effective IT management and plays a crucial role in network security.

When issues occur, quick access to up-to-date information promotes rapid troubleshooting, reducing downtime and support costs.

Equipment Inventories


Accurately track IT assets and rapidly identify EOL (End of Life) equipment for budgeting and planning purposes.



PC Name	Make/Model	CPU	Memory	Service Tag	Date
IMG-ACCT03	DELL Latitude E5470	Dual 2.30 GHz Intel Core i5-6200U	7861 MB	33PGL72	11/8/2016
IMG-ACCT06		Dual 2.50 GHz Intel Core i5-7200U	16267 MB	CVRC9H2	7/31/2017
IMG-SPARESET2	DELL OptiPlex 390	Dual 3.10 GHz Intel Core i3-2100	8165 MB	8BJDJ81	7/31/2017
IMG-ACCT07	DELL Latitude	Dual 2.50 GHz Intel Core i5-7200U	16247 MB	DX07YH2	7/26/2017
IMGTV-TYLER	DELL Latitude	Dual 2.50 GHz Intel Core i5-7200U	16267 MB	F7K93H2	5/28/2017
IMG-LEGAL06	DELL Latitude E5470	Dual 2.30 GHz Intel Core i5-6200U	7861 MB	8G35BG2	1/4/2017
IMG-FINANCE03	DELL OptiPlex 3050	Quad 3.10 GHz Intel Core i7-6700	8052 MB	18F3DD2	8/8/2016
IMG-ACQ02	DELL Latitude E5470	Dual 2.30 GHz Intel Core i5-6200U	11997 MB	BH8VDC2	7/12/2016
IMG-LEGAL05	DELL OptiPlex 3050	Dual 3.20 GHz Intel Core i5-6500	8070 MB	JBMV382	2/25/2016
IMG-LEGAL04	DELL OptiPlex 3050	Dual 3.20 GHz Intel Core i5-6500	8070 MB	JBMY282	2/25/2016
IMG-PROD11	DELL OptiPlex 3050	Dual 3.20 GHz Intel Core i5-6500	8070 MB	JBGS382	2/25/2016
IMG-MARKETING03	DELL OptiPlex 3050	Dual 3.20 GHz Intel Core i5-6500	8070 MB	JBGR282	2/25/2016
IMG-FINANCE02	DELL Latitude E7440	Dual 2.20 GHz Intel Core i5-5200U	4001 MB	5D6BK72	2/15/2016
IMG-ACCT04	DELL Latitude E7440	Dual 2.00 GHz Intel Core i5-4310U	4002 MB	2TJRF12	12/3/2014
IMG-MARKETING06	DELL OptiPlex 3020	Dual 3.30 GHz Intel Core i5-4590	8111 MB	GZDY832	2/5/2015
IMG-ROYALTIES02	Dell OptiPlex 3020	Dual 3.30 GHz Intel Core i5-4590	8111 MB	FSMQH32	2/5/2015
IMG-PROD02	DELL OptiPlex 7010	Dual 3.20 GHz Intel Core i5-3470	3992 MB	24N6NZ1	11/27/2013
IMG-PROD01	DELL OptiPlex 7010	Dual 3.20 GHz Intel Core i5-3470	3992 MB	2SBNNZ1	11/27/2013
IMG-MARKET02	DELL OptiPlex 7010	Dual 3.20 GHz Intel Core i5-3470	8079 MB	FFCKSJ2	8/1/2014
IMG-ACCNT01	DELL OptiPlex 7010	Dual 3.20 GHz Intel Core i5-3470	8079 MB	5FV2TJ2	7/23/2014
IMG-WS-ACCT04	DELL OptiPlex 7010	Dual 3.20 GHz Intel Core i5-3470	8079 MB	8ZWZTJ2	7/11/2014
IMG-ACCNT02	DELL Latitude E7440	Dual 1.90 GHz Intel Core i5-4300U	4002 MB	GSFJTZ3	7/11/2014
IMG-WS-BONNIE02	DELL OptiPlex 3010	Dual 3.20 GHz Intel Core i5-3470	3999 MB	JD1BBY1	10/15/2013
IMG-SURVEYING02	DELL OptiPlex 3010	Dual 3.10 GHz Intel Core i5-3450	3991 MB	14HWXV1	11/1/2012
IMG-COLLECTIONS	DELL OptiPlex 380	Dual 3.30 GHz Intel Core i3-2120	8040 MB	9MXSXR1	8/22/2012
IMG-LEGAL03	Dell OptiPlex 390	Dual 3.30 GHz Intel Core i3-2120	3944 MB	HCDVXR1	8/22/2012
IMG-T3-02	DELL Vostro	Dual 2.80 GHz Intel Core i7-2640M	8150 MB	DBFWNT1	7/16/2012
IMG-MARKETING07	DELL OptiPlex 390	Dual 3.30 GHz Intel Core i3-2120	3994 MB	ZXSB9R1	8/10/2012


Rack / Equipment Elevations

Easily pinpoint the location of core networking devices. Equipment elevations are indispensable to remote support efforts, and aid in "walking" non-technical personnel through basic troubleshooting when emergencies occur.



Network Diagrams and Process Overviews

Streamline troubleshooting and the identification of security risks.



Documentation creation services are provided on a flat-fee basis, based on a free assessment of requirements and network topology. Monthly documentation maintenance services are also available.

To request an assessment, call 424.207.5130, contact your Sandbox Technologies Engineer or Consulting CIO, or send an email to projects@sandboxtech.com